

Defective Concrete Blocks

Damien McKay BEng., CEng., MIEI, Dip.LA.
Chartered Engineer

Chartered Member of Engineers Ireland;
Approved Member of The Engineers Ireland Pyrite 'Design Professionals' (DP) Register;
Member of the Association of Consulting Forensic Engineers.
Member of the Insurance Institute of Ireland



HD McKay
Consulting Engineers

'Improving your living environment'

Emergence of the Issue.....

- A call to Local Radio Station enquiring about Pyrite
- Responded with general information
- Highland requested a detailed live discussion
- Discussed Pyrite and Exterior Cracks on Houses
- Overwhelming response from listeners who recognised the symptoms discussed – especially the issue of cracked exterior walls
- Awareness was consequently created to this County wide issue
- Local Representatives, Councillors and TD's
- Meeting with Senior Department of Environment Officials
- Visit from Minister Mr. Coffey T.D.
- Ongoing enquiries and new cases.



Not to be confused with Pyrite.

- The issue we seem to be facing is different from the problem in Leinster
- Rather than it affecting the sub-floor fill and causing floors to crack and heave
- The issue seems to be defective concrete blocks causing defects to the super structure blockwork.



Common Symptoms.

- Sporadic web/mapped like cracking to external walls.
- The cracks are on the external leaf of the external walls only with no corresponding cracks internally.
- Affects on internal fabric in advanced cases.
- Vertical cracks close to the corners which extend from the ground to the roof.
- Horizontal cracks on the gables.



Common Symptoms cont'd..

- The elevations most susceptible to the prevailing winds and rain appear to be the worst affected.
- Expansion at dpc level.
- Lateral displacement/outward movement of the external leaf
- Degradation, crumbling
- Open textured



Examples



Examples



Examples





HD McKay
Consulting Engineers

'Improving your living environment'



HD McKay
Consulting Engineers

'Improving your living environment'



HD MCKAY
Consulting Engineers

'Improving your living environment'



HD MCKAY
Consulting Engineers

'Improving your living environment'











Extent of the Problem.

- Over 170 houses surveyed and confirmed to date.
- Considerable number of units in multiple housing schemes not yet reported.
- The main geographical area in Donegal is the North East of the County.
- Some isolated cases in other parts of the Country.
- Mostly affecting buildings constructed in the period 1999 – 2008.
- One prominent supplier with a small number of cases from one other supplier.

Possible Causes.....

- Low cement content
- High water/cement ratio
- Abundance of Mica and or Phyllite
- Open textured
- Low density
- Porous
- Low compressive strength
- Dimensional properties

Investigative process.

- Initial Preliminary Visual Site Inspection
- Intrusive site investigations
- Preliminary determination of characteristics
- Extraction of samples & Laboratory testing.

Laboratory Testing.

- Compressive Strength
- Freeze/thaw
- Petrographic – (microscopic examination)
- XRD (X-Ray Diffraction to ascertain the crystalline components (mineralogy) of materials.
- Long term expansion
- Render

Findings.

- Blocks easily broken
- Low compressive strength
- High water cement ratio
- Low cement content
- Low resistance to freeze/thaw tests.
- High levels of Muscovite Mica

Muscovite Mica.

- Main material within schist. (The coarse aggregate was primarily schist, which is a metamorphic rock)
- Excessive amounts can be problematic in concrete.
- Findings shown quantities in excess of 30% of the fine grained material is mica.
- The presence of mica dust results in increase water demand, lower strength and lower durability.
- Strength can be reduced by 5% when 1% of mica is present in the concrete [Dewar, 1963].
- Lees [1987] suggests that mica should be no more than 1% of the aggregate when the aggregate is used for concrete.



Standards.

1997 Building Regulations.

Part A Structure

Part D Materials & Workmanship.

I.S. 20:1987 Concrete Building Blocks, I.S. 5 Aggregates in concrete products.

2003 - Replaced by EN 771-3 aggregate concrete masonry units (dense and lightweight aggregates).

Regulation (EU) No. 305/2011

European Union (Construction Products) Regulations 2013.



HD McKay
Consulting Engineers

'Improving your living environment'

Remedial Work.

- Complete removal of defective material.
- Interim measures.

Level of remedial work is dependant upon the extent of the defect.
The building owners circumstances are taken into consideration.

Challenges in the Remedial Work.

- High Costs where immediate structural work is required.
- Sub-structures affected leading to consequential underpinning in extreme cases.
- Confining the work to what is visibly defective.
- Difficulties in Certification.

Consideration of redress options.

- Home Insurance?
- Do nothing
- Guarantee Schemes
- Complete the structural work by building owner.
- Negotiation with supplier etc.
- Mediation
- Litigation

Challenges facing building owners.

- Unable to confirm identity of the supplier.
- No direct contractual arrangement with the supplier.
- Developer or Contractor no longer in business.
- Lack of engagement by the Supplier.
- Cost and complexities in laboratory testing.
- Cost of litigation is expensive.
- Some homes require urgent structural remedial works.
- Reduced Market Value.

What Next.

- Investigations are ongoing.
- The numbers of new cases continue to rise.
- Review and monitoring of existing cases.
- Ongoing discussions with the Department of Environment.
- Consideration of Standards.
- To clearly identify how this occurred and prevent it from happening again.
- Homeowner discussions with mortgage providers.

Thank You!

Contact Information:

HD McKay
Consulting Engineers
Unit 5
The Starlite Business Centre
Derry Road
Letterkenny
Co. Donegal

(M) 087 2832666 / (Ph) 074 9129243

Email: damien@consultingengineers.ie

Website: www.consultingengineer.ie



HD McKAY
Consulting Engineers

'Improving your living environment'